

U.S. Senate

Desk Description and Condition Report

Desk No : **66.00079.000**

Paper Label No.(on shelf bottom): 80

Painted No. (on bottom): N/A

Other identifying labels or marks (specify location): Stretcher: 80, 82, LXXIX / Top: 80, 77 (pencil) / Drawer Bottom: outside - 2, "Case" / Drawer Back: 80 / Drawer Blade: underside - 86

Description of Desk

Dimensions (in inches)

	Overall	Orig. Desk*	Case	Shelf
Height	35 ½	32 7/16		
Width (front)	27 ½	26 9/16	25 13/16	
Width (rear)	26 ¾	25 13/16	25 1/8	
Depth	19 7/8	19 7/8	19 1/16	9 ¾

* Note: Dimensions do not include "booster" blocks added to feet or writing top.

Woods

Primary:

Mahogany ☒

Mahogany veneer ☒

Rosewood veneer ☐

Other Wood (specify): _____

Character of case mahogany:

Plain ☐

Ribbon ☒

Mottled ☐

Crotch ☐

Other ☐

Secondary:

Element	Pine	Ash	Poplar	Mahog	Other
Drawer Sides			✓		
Drawer Bottom			✓		
Drawer Back			✓		
Case Interior	✓				
Drawer Front	✓				

Construction Details

Leg:

Wood Type	rosewood crossband	other crossband	no crossband
mahog. veneer			
solid mahogany			✓
other: _____			

Foot construction: 1-part ☒
 2-part ☐
 5-part ☐
 Other: _____

Double bead on edge of leg:
 Bead: Thick ☐
 Thin ☒
 Leg Thickness: 1 1/8"

Shape of cross-stretcher edges:
 Rounded ☐
 Rectangular ☒

Spindle type:	Thick	Thin	Other
Number	8		2

Joinery of lower drawer blade to case sides:
 single dovetail ☐
 2 dovetails ☐
 3 dovetails ☐
 lap joint ☐
 other: Blind

Shelf molding applied: Yes ☐
 No ☒

Cockbead width on bottom of drawer front:
 Narrow ☐
 Full width ☒

Opening in original top for inkwell: Yes ☐
 No ☒

Roundels: Single piece ("yo-yo" form) ☐
 Applied boss ☒

Inset distance of single bead on desk back panel:
 Side: 1 1/4"
 Top: 1 3/16"
 Bottom: 1 3/16"

No. of Glue Blocks	Case	Stretch'r	Shelf
Original/Old			2
New/Recent			
Missing			

Interior case-side flush with corner block? Yes ☐
 No ☒

Width of drawer-opening offset Right : 7/16"
 Left : 7/16"

Condition of Desk

Structure

Previous breaks in structural elements: Yes ☒
(shown on schematic)

No ☐

Current split or broken elements: Yes ☒
(shown on schematic)

No ☐

Other loose or damaged joinery: Yes ☐
(describe in narrative)

No ☒

Damage to drawer front: Extreme ☒
Moderate ☐
Minor ☐

Drawer lock: relocated on face Yes ☐

Drawer lock: resized on inside Yes ☒

Cockbead on drawer front: Damaged ☒
(show on schematic)

Missing ☒

Loose ☐

Replacements ☒

Replaced drawer-side runners: Yes ☐

No ☒

Replaced case-side runners: Yes ☒

No ☐

Drawer bottom pieced-out at back edge: Yes ☐

No ☒

Wear on Feet	Extreme	Moderate	Minor
Front	✓		
Rear			✓

Number of loose spindles: No: 0

Number of replaced spindles: (show on schematic) No: 2

Replaced veneers and cross-banding: Yes ☒
(show on schematic)

No ☐

Missing veneers and cross-banding: Yes ☐
(show on schematic)

No ☒

Delaminated/loose veneers & cross-banding: Yes ☐
(show on schematic)

No ☒

Shelf supports: Original/old ☒

New/recent ☐

Missing ☐

Spindle support board in case: Yes ☐

No ☒

Finish

Age	Excellent	Good	Fair	Poor
New			✓	
Old			✓	
Unk.				

Note: Describe finish problems in narrative.

Hardware/Attachments

Item	Mismatch	Missing	Damaged
Knob (L)			✓
Knob (R)			✓

Toe cap size:	Right toe: 8A
(modified)	Left toe: 8A